
APPENDIX B PHOTOGRAPHIC DOCUMENTATION



LOCATION	Dining Room	Photograph 1
SUB-LOCATION	Floor, near stove	Date:
SURFACE TYPE	Carpet	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Living Room	Photograph 2
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W003	House 1



LOCATION	Living Room	Photograph 3
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Hall	Photograph 4
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 1




LOCATION	Kitchen	Photograph 5
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Office	Photograph 6
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Kitchen	Photograph 7
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W012	House 1



LOCATION	Kitchen	Photograph 8
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Kitchen	Photograph 9
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Tile	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W014	House 1




LOCATION	Living Room	Photograph 10
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Hallway	Photograph 11
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 1



LOCATION	Yard	Photograph 12
SUB-LOCATION	Downspout near corner of garage	Date:
SURFACE TYPE	Soil	12/27/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDS SG001	House 1




LOCATION	Yard	Photograph 13
SUB-LOCATION	Downspout on southwest corner of the house	Date:
SURFACE TYPE	Soil	12/27/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDS SG002	House 1




LOCATION	Yard	Photograph 14
SUB-LOCATION	Low area just upgradient from storm sewer drop box	Date:
SURFACE TYPE	Soil	12/27/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDS- SG003	House 1



LOCATION	Yard	Photograph 15
SUB-LOCATION	Next to rose bushes near concrete patio in the backyard	Date:
SURFACE TYPE	Soil	12/27/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	-SG005	House 1



LOCATION	Yard	Photograph 16
SUB-LOCATION	Raised bed on north side of the property near the fence	Date:
SURFACE TYPE	Soil	12/27/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDS SG004	House 1




LOCATION	Hallway	Photograph 17
SUB-LOCATION	South Side	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Hallway	Photograph 18
SUB-LOCATION	West Hallway	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDSW018	House 1




LOCATION	Bedroom #2	Photograph 19
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W019	House 1



LOCATION	Bedroom #2	Photograph 20
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W020	House 1



LOCATION	Bedroom #2	Photograph 21
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W022	House 1



LOCATION	Bedroom #2	Photograph 22
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Bedroom #2	Photograph 23
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/27/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Master Bedroom	Photograph 24
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Office	Photograph 25
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W031	House 1




LOCATION	Master Bedroom	Photograph 26
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Office	Photograph 27
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Master Bedroom	Photograph 28
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W045	House 1



LOCATION	Office	Photograph 29
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W034	House 1




LOCATION	Master Bedroom	Photograph 30
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W042	House 1



LOCATION	Master Bedroom	Photograph 31
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Master Bedroom	Photograph 32
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Master Bedroom	Photograph 33
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W045	House 1




LOCATION	Master Bathroom	Photograph 34
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Master Bathroom	Photograph 35
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W046	House 1




LOCATION	Master Bathroom	Photograph 36
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Linen Closet	Photograph 37
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Linen Closet	Photograph 38
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Kitchen Entrance	Photograph 39
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W036	House 1



LOCATION	Main Entrance	Photograph 40
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W048	House 1




LOCATION	Basement- Main	Photograph 41
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W065	House 1




LOCATION	Basement- Main	Photograph 42
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W064	House 1



LOCATION	Basement-Main	Photograph 43
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Wood Panel- Pained	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Basement-Main	Photograph 44
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Basement-Main	Photograph 45
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Carpet	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W061	House 1



LOCATION	Basement Bedroom	Photograph 46
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W059	House 1




LOCATION	Basement Bedroom	Photograph 47
SUB-LOCATION	West Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W058	House 1




LOCATION	Basement Bedroom	Photograph 48
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W060	House 1




LOCATION	Basement Bedroom	Photograph 49
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W057	House 1




LOCATION	Basement Bedroom	Photograph 50
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDSW056	Property: House 1




LOCATION	Basement Bedroom	Photograph 51
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Concrete - Painted	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Workshop/Utility Room	Photograph 52
SUB-LOCATION	North Wall	Date:
SURFACE TYPE	Wood Paneling	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Utility/Workshop	Photograph 53
SUB-LOCATION	East Wall	Date:
SURFACE TYPE	Wood Paneling	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Workshop/Utility Room	Photograph 54
SUB-LOCATION	South Wall	Date:
SURFACE TYPE	Wood Paneling	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W068	House 1




LOCATION	Garage	Photograph 55
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Garage	Photograph 56
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Concrete	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W074	House 1



LOCATION	Garage	Photograph 57
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1



LOCATION	Garage	Photograph 58
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W071	House 1




LOCATION	Garage	Photograph 59
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/28/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 1




LOCATION	Yard	Photograph 60
SUB-LOCATION	Front yard 5 alignment composite	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil sample, composite	Property:
SAMPLE ID	-C-S001	House 2



LOCATION	Yard	Photograph 61
SUB-LOCATION	Front yard 5 alignment composite	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, composite	Property:
SAMPLE ID	BDSC-S001	House 2



LOCATION	Yard	Photograph 62
SUB-LOCATION	Downspout at NW corner of home	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	-G-S007	House 2



LOCATION	Yard	Photograph 63
SUB-LOCATION	Soil near outlet to storm sewer box	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDS-G-S004	House 2



LOCATION	Yard	Photograph 64
SUB-LOCATION	Lower of circular flower bed near phone pedestal	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDSG-S005	House 2




LOCATION	Yard	Photograph 65
SUB-LOCATION	Downspout at SE corner of house	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	BDSG-S003	House 2




LOCATION	Yard	Photograph 66
SUB-LOCATION	Near north side of flower bed (roses)	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, grab	Property:
SAMPLE ID	-G-S006	House 2



LOCATION	Yard	Photograph 67
SUB-LOCATION	Back yard composite 5-alignment composite	Date:
SURFACE TYPE	Soil	12/28/2016
SAMPLE TYPE	Soil, composite	Property:
SAMPLE ID	BDSC-S002	House 2




LOCATION	Kitchen	Photograph 68
SUB-LOCATION	Countertop	Date:
SURFACE TYPE	Granite	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W002	Property: House 2




LOCATION	Kitchen	Photograph 69
SUB-LOCATION	Backsplash	Date:
SURFACE TYPE	Granite	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 2




LOCATION	Kitchen	Photograph 70
SUB-LOCATION	Entrance, Back	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Living Room	Photograph 71
SUB-LOCATION	Entrance, Main	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Kitchen	Photograph 72
SUB-LOCATION	Entrance, Garage	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W005	Property: House 2




LOCATION	Dining Room	Photograph 73
SUB-LOCATION	Entrance, Back	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDSW006	House 2




LOCATION	Dining Room	Photograph 74
SUB-LOCATION	Fireplace, Brick Base	Date:
SURFACE TYPE	Brick	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W008	House 2



LOCATION	Dining Room	Photograph 75
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W010	House 2



LOCATION	Dining Room	Photograph 76
SUB-LOCATION	Fireplace, Brick Wall	Date:
SURFACE TYPE	Brick	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Living Room	Photograph 77
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W013	House 2




LOCATION	Dining Room	Photograph 78
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W012	House 2




LOCATION	Dining Room	Photograph 79
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Living Room	Photograph 80
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W017	House 2



LOCATION	Living Room	Photograph 81
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Living Room	Photograph 82
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Hall	Photograph 83
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 2



LOCATION	Hall	Photograph 84
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 2




LOCATION	Hall Bathroom	Photograph 85
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 2




LOCATION	Hall	Photograph 86
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W026	House 2




LOCATION	Hall	Photograph 87
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W027	Property: House 2




LOCATION	Hall Bathroom	Photograph 88
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Master Bedroom	Photograph 89
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Hall Bathroom	Photograph 90
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Master Bedroom	Photograph 91
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W029	House 2



LOCATION	Hall Bathroom	Photograph 92
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W022	House 2



LOCATION	Master Bedroom	Photograph 93
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Master Bedroom	Photograph 94
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W030	House 2




LOCATION	Master Bedroom	Photograph 95
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W032	House 2




LOCATION	Hall Linen Closet	Photograph 96
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Bedroom 2	Photograph 97
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W035	House 2



LOCATION	Bedroom 2	Photograph 98
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	Property: House 2



LOCATION	Hall Linen Closet	Photograph 99
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W024	House 2



LOCATION	Bedroom 2	Photograph 100
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W038	House 2





LOCATION	Bedroom 2	Photograph 101
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Bedroom 2	Photograph 102
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Bedroom 1	Photograph 103
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W043	House 2



LOCATION	Bedroom 1	Photograph 104
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W042	House 2




LOCATION	Bedroom 1	Photograph 105
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Bedroom 1	Photograph 106
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W044	House 2



LOCATION	Bedroom 1	Photograph 107
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Master Closet	Photograph 108
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Hardwood	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W046	House 2




LOCATION	Master Closet	Photograph 109
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS- W047	House 2



LOCATION	Master Bathroom	Photograph 110
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Tile	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2




LOCATION	Master Bathroom	Photograph 111
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W050	House 2



LOCATION	Master Bathroom	Photograph 112
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W049	House 2



LOCATION	Master Bathroom	Photograph 113
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS- W052	House 2




LOCATION	Basement	Photograph 114
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W065	House 2



LOCATION	Basement	Photograph 115
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W064	House 2




LOCATION	Basement	Photograph 116
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS W063	House 2



LOCATION	Basement	Photograph 117
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDSW062	House 2



LOCATION	Basement	Photograph 118
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Basement Utility	Photograph 119
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2



LOCATION	Basement Utility	Photograph 120
SUB-LOCATION	Wall	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W053	House 2






LOCATION	Garage	Photograph 121
SUB-LOCATION	Wall, East	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W057	House 2



LOCATION	Garage	Photograph 122
SUB-LOCATION	Floor	Date:
SURFACE TYPE	Concrete	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS- W055	Property: House 2





LOCATION	Garage	Photograph 123
SUB-LOCATION	Wall, North	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS -W054	House 2



LOCATION	Garage	Photograph 124
SUB-LOCATION	Wall, South	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS-W056	House 2



LOCATION	Garage	Photograph 125
SUB-LOCATION	Wall, West	Date:
SURFACE TYPE	Drywall	12/29/2016
SAMPLE TYPE	Wipe	Property:
SAMPLE ID	BDS	House 2